

Subject: Transmission Owner Emergency Notifications

When disturbance events occur on the system, the NYISO and the Transmission Owners must share information to ascertain the state of the system and to provide clear notification to the appropriate groups.

Background:

The NYISO is responsible for the continuous monitoring and assessment of conditions on the New York State Transmission System. When disturbance events occur on the system, the NYISO and the Transmission Owners must share information to better ascertain the state of the system and to provide clear notification to appropriate groups.

In order to facilitate the NYISO's duty to communicate system conditions and status with federal and state government agencies, as well as internally and with interconnected systems, Transmission Owners shall notify the NYISO of significant disturbance events on their systems.

Details:

The NYISO and the Transmission Owners are required to file reports to the Department of Energy (DOE) for events that are identified and listed in the DOE Form OE-417.

In the case of Bulk Power System Events, the NYISO will collect information readily available at the Power Control Center and may request supporting information from the appropriate Transmission Owners if needed. Events which are directed by the NYISO such as load shedding and voltage reduction for Bulk Power System events need not be reported by the Transmission Owners. The NYISO will report on behalf of the New York Control Area.

Events on facilities *not* considered part of the Bulk Power System may still require DOE OE-417 reporting by a Transmission Owner. The NYISO needs to be made aware of these events and may need to report on them. To ensure information flow and consistency, Transmission Owners will send copies of their OE-417 reports to the NYISO when issuing these reports to the DOE.

Method and Timing of Reporting:

Transmission Owner System Operators will verbally notify NYISO Operators of local conditions and system status. If unilateral corrective action by the Transmission Owner(s) is required as a result of a violation severe enough to require immediate action, the

The purpose of this "Technical Bulletin" is to facilitate participation in the NYISO by communicating various NYISO concepts, techniques, and processes to Market Participants before they can be formally documented in a NYISO manual. The information contained in this bulletin is subject to change as a result of a revision to the ISO Tariffs or a subsequent filed tariff with the FERC.

Transmission Owner System Operators must keep the NYISO Shift Supervisor informed as soon as the initial event has been secured.

Transmission Owner System Operators will e-mail copies of their DOE Form OE – 417 reports to reliabilitycompliance@nyiso.com with the subject line: *OE - 417*. In the event that e-mail is not functioning, the form will be faxed to 518-356-6237. These reports shall be made concurrent with DOE reporting.