

NYISO Major Emergency Report

At **1610** On **Thursday 8/ 14/03** a Major Emergency was declared by the NYISO Shift Supervisor

System separation occurred causing the loss of load and generation in the NYCA.

This was caused when:

larger power swings of 700MW and 1100 MW were observed flowing into NYISO from PJM and west into IMO. This was followed by 3000 MW swing out of IMO towards PJM. Ties with PJM and ISONE tripped and IMO was radial on the NYCA.

To correct this, the ISO Shift Supervisor:

entered into system restoration procedures and began system restoration. A number of actions were taken as defined by NYISO Procedures.

Load Relief Was Required.

The Major Emergency was terminated at **08/18**