

NYISO Major Emergency Report

At 08:05 on 07/20/2009

A Major Emergency was declared by the NYISO Shift Supervisor

when the power flow on L34P Saunders-Moses St Lawrence exceeded its LTE Rating

1 minute

This was caused when:

IESO moved the phase angle regulator (PAR) taps on L34P Saunders-Moses St. Lawrence 230kv line resulting in an overload on the facility.

To correct this, the ISO Shift Supervisor:

IESO reversed the move on the PAR taps to unload line L34P

Load Relief Was Not Required.

The Major Emergency was terminated at 08:05