## Meter Inventory Database: A Step to Alternatives

**Business Issues Committee Meeting** 

May 7, 2003

Agenda #12

J. Scheiderich

- ➤ BIC/BAWG should complete a review of the Meter Inventory and existing/proposed standards and, if found lacking to support settlement in an accurate *and* timely manner, the following should be considered:
  - NYISO should consider settling loads based on integrated State Estimator flow values.
  - Other possibilities

- ➤ Why not just bring metering up to state-of-the-art standards for accuracy, calibration and testing?
  - ➤ It is possible that we will not agree on mutually acceptable standards
  - Costs to bring the system into wide spread compliance could be prohibitive and would likely take years
  - ➤ In all fairness, the ISO needs to review how much lack of accuracy in the metering contributes to BOTH delay in settlement and unfair settlements for LSEs

- ➤ How would using a State Estimator help?
  - ✓ The ISO would calculate flows from integrated SE results
  - ✓ State Estimators use statistical processing that allow for both bad data detection and correction (depending on meter redundancy). Further, they allow for weighting of specific meter contribution to the solution,
  - ✓ PJM has used this approach from Day 1 and as it is understood, the SE based values are in fact the final numbers used,
- ➤ Would we just ignore metering that is believed to be accurate?
  - ✓ No. SE and Meter values could be compared and BOTH the software and meters would be subject to calibration checks

Note: ConEd uses their SE results on their intra-zonal ties for settlement now

## ➤ What other possibilities are there?

- ✓ Modify settlement such that Non-TO LSEs are removed from sharing any energy shifts resulting from meter related issues
- ✓ Basically, non-TO LSEs would be responsible for end use energy adjusted for tariff based losses
- ✓ This would then leave the TOs responsible for meter errors and related adjustments
- ✓ Since, in most cases the TOs are and will remain the Meter Authority for sub-zone tie lines, it would be appropriate to leave them to deal with the issue in any manner they choose...